

## JOINT MACHINES

### GRAVITATIONAL BAND SAW MACHINE

Manually controlled quick clamping vice, cut is regulated by a hydraulic damper and a restrictor choke valve. A course of a cut is not influenced by a human factor and it causes a higher bladeflife. A operator starts a machine pressing button START and sets a cutting speed. After finishing the cut machines stops itself automatically and an operator lifts the arm manually to the start position. Feeding of material is manual. Angle cuts are possible by arm turning.



	mm	0°	45°	60°	-45°	-60°
220x250 GH-R	∅	220	160	90	x	x
230x280 GH-LR	∅	230	190	100	170	x
250x315 GH-LR	∅	250	190	120	170	x
300x320 GH-LR	∅	300	300	200	270	x
360x500 GH-LR	∅	360	360	300	360	300

PEGAS-GONDA s.r.o.  
 Čs. armády 322, 684 01 Slavkov u Brna  
[www.pegas-gonda.cz](http://www.pegas-gonda.cz)  
 Tel.: 00420-544 221 125(6), E-mail: [pegas@gonda.cz](mailto:pegas@gonda.cz)